

Date of Report : 02/11/2021

**Page 1 of 18** 

# **TEST REPORT**

CLIENT DETAILS

LABORATORY DETAILS

Client Name:NSL Textiles LtdSGS Affiliate:SGS India Pvt Ltd., ChennaiClient Contact:Punidha Kumar.RSGS Contact:Balla Suresh Kumar

**Telephone**: +91 9581412155 **Telephone**: +91 9840830472

Email: <u>Punidhakumar.r@nsltextiles.com</u> Email: <u>balla.sureshkumar@sgs.com</u>

Servey No: 371-378 KunchalavariPalem,

28 B/1(SP), 28B/2 (SP),

Canada Main Board, Amban

Address:

Chandole Post, Cherukupalli (MD), Guntur

Address:

Second Main Road, Ambattur, Chennai-

(Dist), Andhra Pradhesh - 522311

58.

**FACTORY DETAILS** 

Factory Name:
NSL Textiles Ltd
Factory Contact:
Punidha Kumar.R
+91 9581412155

Email: Punidhakumar.r@nsltextiles.com

Address:

Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli

(MD), Guntur (Dist), Andhra Pradhesh - 522311

**Types of Mills:**Zero Liquid Discharge Treatment

(4) Fabric Dyeing, Finishing, Printing

SAMPLE AND TESTING DETAILS

Sampling Country: SGS India Pvt. Ltd.,

**Sampling Engineer / ZDHC Sampler's** 

PUGAZHENTHI M/8F146507676

Sampling Date: 25-10-2021
Sample Received Date: 26-10-2021

Test Performing Period: 25-10-2021 - 02-11-2021

No. of Samples: Water (1); Sludge (1)

Sample Descriptions:

1) Raw Wastewater (6-hour Composite)

2) Sludge (Grab)

Sample Volume 8L Water sample; 2 Kg Sludge

**Testing Institute:** SGS India Pvt. Ltd.., Chennai CRS Lab/Multilab

Discharge Method: Zero Liquid Discharge

**OVERALL RESULTS** 

**Certification No.:** 

	Raw Wastewater	Sludge
Anions / Metals:	Exceed Foundational Limit	Not Detected
MRSL Parameters:	Not Detected	Not Detected

# REMARKS

- 1. This test document cannot be reproduced in any way, except in full content, without prior approval in writing by the laboratory.
- 2. The results shown in this test report refer only to the sampling and the sample(s) tested unless otherwise stated.

Per pro SGS India Private Ltd

P.SHANMUGAM EXECUTIVE

Email your Test Report Related Enquiries at Feedback.SLT@sgs.com

JOE No. : 2142821649 Control No:1242544637

This document is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at <a href="http://www.sgs.com/">http://www.sgs.com/</a> terms\_and\_conditions.htm and and Terms and Conditions for electronic documents www.sgs.com/terms\_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. This document cannot be reproduced except in full, without prior approval of the Company.

SGS India Pvt. Ltd. Consumer and Retail, Testing Laboratory, 28 B/1(SP), 28 B/2(SP), Second Main Road, Ambattur Industrial Estate, Ambattur, Chennai - 600 058. India t: (91 -44) 6608 1600



Date of Report: 02/11/2021

**Page 2 of 18** 

#### **RESULT SUMMARY**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra

Pradhesh - 522311

TEST ITEMS	Raw Wastewater	Sludge
Anions	-	0
Metals	X	0
Alkylphenol (AP) & Alkylphenol Ethoxylates (APEOs)	0	0
Chlorobenzenes and Chlorotoluenes	0	0
Chlorophenols	0	0
Dyes - Azo (Forming Restricted Amines)	0	0
Dyes - Carcinogenic or Equivalent Concern	0	0
Dyes - Disperse (Sensitising)	0	0
Flame Retardants	0	0
Glycols	0	0
Halogenated Solvents	0	0
Organotin Compounds	0	0
Perfluorinated and Polyfluorinated Chemicals (PFCs)	0	0
Ortho-Phthalates	0	0
Polycyclic Aromatic Hydrocarbons (PAHs)	0	0
Volatile Organic Compounds (VOCs)	0	0

#### Note:

X - Detected

O - Not Detected

N/A - Not Tested



Date of Report : 02/11/2021

**Page 3 of 18** 

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
			pling Location	Wasta Water Refere	-	-	Sludge - Decenter Sludge Room		
		Samp	ling Start Time		-	-	14:30	Factory Per	formances
			oling End Time		-	-	14:40		
			nple Received		-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Sample Colour Description	-	-	-	Green	-	-	Dk. Green	-	-
Anions									
Cyanide	-	0.05	mg/L	-	1	mg/kg	n.d.	-	Not Detected
Metals									
Total Antimony (Sb)*	7440-36-0	0.01	mg/L	n.d.	-	-	-	Fulfill Aspirational Limit	-
Total Chromium (Cr)	7440-47-3	0.05	mg/L	1.20	-	-	-	Exceed Foundational Limit	-
Total Cobalt (Co)	7440-48-4	0.01	mg/L	n.d.	-	-	-	Fulfill Aspirational Limit	-
Total Copper (Cu)	7440-50-8	0.25	mg/L	0.39	-	-	-	Fulfill Progressive Limit	-
Total Nickel (Ni)	7440-02-0	0.05	mg/L	n.d.	-	-	-	Fulfill Aspirational Limit	-
Total Silver (Ag)	7440-22-4	0.005	mg/L	n.d.	-	-	-	Fulfill Aspirational Limit	-
Total Zinc (Zn)	7440-66-6	0.5	mg/L	n.d.	-	-	-	Fulfill Aspirational Limit	-
Total Arsenic (As)	7440-38-2	0.005	mg/L	n.d.	2	mg/kg	n.d.	Fulfill Aspirational Limit	Not Detected
Total Cadmium (Cd)	7440-43-9	0.01	mg/L	n.d.	2	mg/kg	n.d.	Fulfill Aspirational Limit	Not Detected
Chromium-Hexavalent (Cr-VI)	7440-47-3, 18540-29-9	0.001	mg/L	n.d.	2	mg/kg	n.d.	Fulfill Aspirational Limit	Not Detected
Total Lead (Pb)	7439-92-1	0.01	mg/L	n.d.	2	mg/kg	n.d.	Fulfill Aspirational Limit	Not Detected
Total Mercury (Hg)	7439-97-6	0.001	mg/L	n.d.	0.2	mg/kg	n.d.	Fulfill Aspirational Limit	Not Detected
Alkylphenol (AP) & Alkylphenol Ethox	xylates (APEOs) Multiple, including 104-40-								
Nanylphonal (NP) mixed isomore	5, 11066-49-2, 25154-52- 3, 84852-15-3, 90481-04- 2, 1173019-62-9	5	μg/L	n.d.	0.4	mg/kg	n.d.	Not Detected	Not Detected
	Multiple, including 140-66-9, 1806-26-4, 27193-28-8	5	μg/L	n.d.	0.4	mg/kg	n.d.	Not Detected	Not Detected
Octylphenol ethoxylates (OPEO)	Multiple, including 9002-93- 1, 9036-19-5, 68987-90-6	5	μg/L	n.d.	0.4	mg/kg	n.d.	Not Detected	Not Detected
	Multiple, including 9016-45-9, 26027-38-3, 37205-87-1, 68412-54-4, 127087-87-0	5	μg/L	n.d.	0.4	mg/kg	n.d.	Not Detected	Not Detected



Date of Report : 02/11/2021 Page 4 of 18

# **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			0	4040040544(4)			10100105111(D)		
		Da	Sample ID te of Sampling		•	-	1242040514 (B) 25-10-2021		
				Waste Water Refere	-	-	Sludge - Decenter		
			pling Location	rreatment - ripe Line	-	-	Sludge Room	Factory Per	formances
			ling Start Time		-	-	14:30	-	
			mple Received		-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Chlorobenzenes & Chlorotoluenes									
Monochlorobenzenes	108-90-7	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2-Dichlorobenzene	95-50-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,3-Dichlorobenzene	541-73-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,4-Dichlorobenzene	106-46-7	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2,3-Trichlorobenzene	87-61-6	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2,4-Trichlorobenzene	120-82-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,3,5-Trichlorobenzene	108-70-3	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2,3,4-Tetrachlorobenzene	634-66-2	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2,3,5-Tetrachlorobenzene	634-90-2	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
1,2,4,5-Tetrachlorobenzene	95-94-3	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Pentachlorobenzene	608-93-5	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Hexachlorobenzene	118-74-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2-Chlorotoluene	95-49-8	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3-Chlorotoluene	108-41-8	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4-Chlorotoluene	106-43-4	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3-Dichlorotoluene	32768-54-0	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,4-Dichlorotoluene	95-73-8	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,5-Dichlorotoluene	19398-61-9	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,6-Dichlorotoluene	118-69-4	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,4-Dichlorotoluene	95-75-0	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,5-Dichlorotoluene	25186-47-4	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3,4-Trichlorotoluene	7359-72-0	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3,6-Trichlorotoluene	2077-46-5	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,4,5-Trichlorotoluene	6639-30-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected

This document is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at <a href="http://www.sgs.com/">http://www.sgs.com/</a> terms\_and\_conditions.htm and and Terms and Conditions for electronic documents www.sgs.com/terms\_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. This document cannot be reproduced except in full, without prior approval of the Company.

SGS India Pvt. Ltd. Consumer and Retail, Testing Laboratory, 28 B/1(SP), 28 B/2(SP), Second Main Road, Ambattur Industrial Estate, Ambattur, Chennai - 600 058. India t: (91 -44) 6608 1600



Date of Report : 02/11/2021

**Page 5 of 18** 

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Da	te of Sampling	` ,	-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room		
			ling Start Time		-	-	14:30	- Factory Per	formances
		Samp	oling End Time	14:00	-	-	14:40	1	
		Date of Sar	mple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
2,4,6-Trichlorotoluene	23749-65-7	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,4,5-Trichlorotoluene	21472-86-6	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3,4,5-Tetrachlorotoluene	76057-12-0	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3,5,6-Tetrachlorotoluene	29733-70-8	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,3,4,6-Tetrachlorotoluene	875-40-1	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Pentachlorotoluene	877-11-2	0.2	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Chlorophenols									
2-Chlorophenol	95-57-8	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
3-Chlorophenol	108-43-0	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
4-Chlorophenol	106-48-9	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3-Dichlorophenol	576-24-9	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,4-Dichlorophenol	120-83-2	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,5-Dichlorophenol	583-78-8	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,6-Dichlorophenol	87-65-0	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
3,4-Dichlorophenol	95-77-2	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
3,5-Dichlorophenol	591-35-5	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3,4-Trichlorophenol	15950-66-0	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3,5-Trichlorophenol	933-78-8	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3,6-Trichlorophenol	933-75-5	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,4,5-Trichlorophenol	95-95-4	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,4,6-Trichlorophenol	88-06-2	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
3,4,5-Trichlorophenol	609-19-8	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3,4,5-Tetrachlorophenol	4901-51-3	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected



**Page 6 of 18** 

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)		-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room		
		Samp	ling Start Time		-	-	14:30	Factory Per	formances
		Samp	oling End Time	14:00	-	-	14:40		
		Date of Sai	mple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
2,3,4,6-Tetrachlorophenol	58-90-2	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
2,3,5,6-Tetrachlorophenol	935-95-5	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
Pentachlorophenol	87-86-5	0.5	μg/L	n.d.	0.05	mg/kg	n.d.	Not Detected	Not Detected
Dyes - Azo (Forming Restricted Amine	es)								
4,4'-Methylene-Bis(2-Chloroaniline)	101-14-4	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4,4'-Diaminodiphenylmethane	101-77-9	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4,4'-Oxydianiline	101-80-4	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
p-Chloroaniline	106-47-8	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,3'-Dimethoxybenzidine	119-90-4	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,3'-Dimethylbenzidine	119-93-7	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
p-Cresidine	120-71-8	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,4,5-Trimethylaniline	137-17-7	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4,4'-Thiodianiline	139-65-1	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
p-Aminoazobenzene	60-09-3	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,4-Diaminoanisole	615-05-4	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,3'-Dimethyl- 4,4'diaminodiphenylmethane	838-88-0	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,6-Xylidine	87-62-7	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
o-Anisidine	90-04-0	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2-Naphthylamine	91-59-8	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
3,3'-Dichlorobenzidine	91-94-1	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4-Aminodiphenyl	92-67-1	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzidine	92-87-5	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
o-Toluidine	95-53-4	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected



Page 7 of 18

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room		
		Samp	ling Start Time		-	-	14:30	Factory Per	formances
			oling End Time	14:00	-	-	14:40		
		Date of Sa	mple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
2,4-Xylidine	95-68-1	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
4-Chloro-o-Toluidine	95-69-2	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2,4-Toluylenediamine	95-80-7	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
o-Aminoazotoluene	97-56-3	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
2-Amino-4-Nitrotoluene	99-55-8	0.1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Dyes - Carcinogenic or Equivalent Co	oncern								
Direct Black 38	1937-37-7	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Direct Blue 6	2602-46-2	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Acid Red 26	3761-53-3	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Red 9	569-61-9	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Direct Red 28	573-58-0	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Violet 14	632-99-5	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 1	2475-45-8	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 3	2475-46-9	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Blue 26	2580-56-5	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Green 4 (malachite green chloride)^	569-64-2	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Green 4 (malachite green oxalate)^	2437-29-8	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Basic Green 4 (malachite green)	10309-95-2	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Disperse Orange 11	82-28-0	500	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Dyes - Disperse (Sensitising)									
Disperse Yellow 1	119-15-3	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 102	12222-97-8	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 106	12223-01-7	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Yellow 39	12236-29-2	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected



Date of Report : 02/11/2021 **Page 8 of 18** 

# **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Dat	te of Sampling		-	-	25-10-2021		
				Waste Water Refore	-	-	Sludge - Decenter		
			pling Location	Treatment - Pipe Line	-	-	Sludge Room	Factory Per	formances
			ling Start Time		-	-	14:30		
			oling End Time		-	-	14:40		
		Date of Sar	nple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Disperse Orange 37/59/76	13301-61-6	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Brown 1	23355-64-8	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Orange 1	2581-69-3	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Yellow 3	2832-40-8	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Red 11	2872-48-2	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Red 1	2872-52-8	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Red 17	3179-89-3	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 7	3179-90-6	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 26	3860-63-7	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Yellow 49	54824-37-2	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 35	12222-75-2, 56524-77-7	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Blue 124	61951-51-7	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Yellow 9	6373-73-5	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Disperse Orange 3	730-40-5	50	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Flame Retardants									
Tris(2-chloroethyl) phosphate (TCEP)	115-96-8	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Decabromodiphenyl ethers (DecaBDE)	1163-19-5	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Tris(2,3-dibromopropyl) phosphate (TRIS)	126-72-7	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Pentabromodiphenyl ethers (PentaBDE)	32534-81-9	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Octabromodiphenyl ethers (OctaBDE)	32536-52-0	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected



Date of Report : 02/11/2021

**Page 9 of 18** 

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room	1	
		Samp	ling Start Time	8:00	-	-	14:30	Factory Per	formances
		Samp	oling End Time	14:00	-	-	14:40	1	
		Date of Sar	mple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Bis(2,3-dibromopropyl)phosphate (BIS)	5412-25-9	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Tris(1-aziridinyl)phosphine oxide) (TEPA)	545-55-1	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Polybrominated biphenyls (PBBs)	59536-65-1	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Tetrabromobisphenol A (TBBPA)	79-94-7	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Hexabromocyclododecane (HBCDD)	134237-50-6, 134237-51-7, 134237-52-8, 25637-99-4, 3194-55-6	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
2,2-Bis(bromomethyl)-1,3-propanediol (BBMP)	3296-90-0	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Tris(1,3-dichloro-2-propyl) phosphate (TDCPP)	13674-87-8	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Short Chain Chlorinated Paraffins (SCCP), C <sub>10</sub> -C <sub>13</sub>	85535-84-8	5	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Glycols									
Bis(2-methoxyethyl)-ether	111-96-6	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
2-Ethoxyethanol	110-80-5	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
2-Ethoxyethyl acetate	111-15-9	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Ethylene glycol dimethyl ether	110-71-4	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
2-Methoxyethanol	109-86-4	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
2-Methoxyethylacetate	110-49-6	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
2-Methoxypropylacetate	70657-70-4	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Triethylene glycol dimethyl ether	112-49-2	50	μg/L	n.d.	10	mg/kg	n.d.	Not Detected	Not Detected
Halogenated Solvents									
1,2-Dichloroethane	107-06-2	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Methylene chloride	75-09-2	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Trichloroethene	79-01-6	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Tetrachloroethene	127-18-4	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected



Page 10 of 18

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			0 1 10						
			Sample ID		-	-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room	Factory Pe	formances
		Samp	ling Start Time	8:00	-	-	14:30		
		Samp	oling End Time	14:00	-	-	14:40		
		Date of Sar	nple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Organotin Compounds									
Mono-, di- and tri-methyltin derivatives	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Monomethyltin (MMT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Dimethyltin (DMT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Trimethyltin (TMT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Mono-, di- and tri-butyltin derivatives	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Monobutyltin (MBT)	1118-46-3, 78763-54-9	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Dibutyltin (DBT)	1002-53-5	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Tributyltin (TBT)	56573-85-4	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Mono-, di- and tri-phenyltin derivatives	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Monophenyltin (MPhT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Diphenyltin (DPhT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Triphenyltin (TPhT)	892-20-6, 668-34-8	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Mono-, di- and tri-octyltin derivatives	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Monooctyltin (MOT)	15231-57-9	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Dioctyltin (DOT)	94410-05-6, 12531-44-4	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Trioctyltin (TOT)	Multiple	0.01	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Perfluorinated and Polyfluorinated Ch	nemicals (PFCs)								
PFOS	1763-23-1	0.01	μg/L	n.d.	0.10	mg/kg	n.d.	Not Detected	Not Detected
PFOA	335-67-1	0.01	μg/L	n.d.	0.10	mg/kg	n.d.	Not Detected	Not Detected
PFBS	375-73-5, 59933-66-3, 29420-49-3, 29420-43-3	0.01	μg/L	n.d.	0.10	mg/kg	n.d.	Not Detected	Not Detected



Page 11 of 18

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)		-	1242040514 (B)		
		Da	te of Sampling	25-10-2021	-	-	25-10-2021	1	
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room	Factory Per	formances
		Samp	ling Start Time	8:00	-	-	14:30		
		Samp	oling End Time	14:00	-	-	14:40		
		Date of Sar	nple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
PFHxA	307-24-4	0.01	μg/L	n.d.	0.10	mg/kg	n.d.	Not Detected	Not Detected
8:2 FTOH	678-39-7	1	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
6:2 FTOH	647-42-7	1	μg/L	n.d.	1	mg/kg	n.d.	Not Detected	Not Detected
Ortho-Phthalates									
Di(2-Ethyl Hexyl) Phthalate (DEHP)	117-81-7	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Bis(2-methoxyethyl)phthalate (DMEP)	117-82-8	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-N-Octyl Phthalate (DNOP)	117-84-0	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-Iso-Decyl Phthalate (DIDP)	26761-40-0, 68515-49-1	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-Iso-Nonyl Phthalate (DINP)	28553-12-0, 68515-48-0	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-N-Hexyl Phthalate (DNHP)	84-75-3	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Dibutyl Phthalate (DBP)	84-74-2	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Benzyl Butyl Phthalate (BBP)	85-68-7	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Dinonyl phthalate (DNP)	84-76-4	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Diethyl Phthalate (DEP)	84-66-2	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-N-Propyl Phthalate (DPRP)	131-16-8	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-Iso-Butyl Phthalate (DIBP)	84-69-5	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected



Page 12 of 18

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Da	te of Sampling		-	-	25-10-2021		
		Sam	pling Location	Waste Water Before Treatment - Pipe Line	-	-	Sludge - Decenter Sludge Room		
		Samp	ling Start Time		-	-	14:30	Factory Per	formances
		Samp	oling End Time	14:00	-	-	14:40		
		Date of Sai	nple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Dicyclohexyl Phthalate (DCHP)	84-61-7	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Di-Iso-Octyl Phthalate (DIOP)	27554-26-3	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
1,2-Benzenedicaboxylic acid, Di-C7-11 Branched and Linear Alkyl Esters (DHNUP)	68515-42-4	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
1,2-Benzenedicaboxylic acid, Di-C6-8 Branched Alkyl Esters, C7-rich (DIHP)	71888-89-6	10	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Polycyclic Aromatic Hydrocarbons (F	AHs)								
Bezno[a]pyrene	50-32-8	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Anthracene	120-12-7	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Pyrene	129-00-0	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[ghi]perylene	191-24-2	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[e]pyrene	192-97-2	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Indeno[1,2,3-cd]pyrene	193-39-5	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[j]fluoranthene	205-82-3	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[b]fluoranthene	205-99-2	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Fluoranthene	206-44-0	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[k]fluoranthene	207-08-9	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Acenaphthylene	208-96-8	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Chrysene	218-01-9	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Dibenz[a,h]anthracene	53-70-3	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Benzo[a]anthracene	56-55-3	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Acenaphthene	83-32-9	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Phenanthrene	85-01-8	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Fluorene	86-73-7	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected
Naphthalene	91-20-3	1	μg/L	n.d.	0.2	mg/kg	n.d.	Not Detected	Not Detected



Date of Report: 02/11/2021

Page 13 of 18

#### **TEST RESULTS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post,

Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

			Sample ID	1242040514 (A)	-	-	1242040514 (B)		
		Date of Sampling			-	-	25-10-2021	Factory Performances	
	Mosta Motor Defers			-	-	Sludge - Decenter Sludge Room			
				8:00	-	-	14:30		
		Samp	oling End Time	14:00	-	-	14:40		
		Date of Sar	nple Received	26-10-2021	-	-	26-10-2021		
Items	CAS No.	Reporting Limit	Units	Raw Wastewater	Reporting Limit	Units	SludgeΦ	Raw Wastewater	Sludge
Volatile Organic Compounds (VOCs)									
Benzene	71-43-2	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Xylene	1330-20-7	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
o-cresol	95-48-7	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
p-cresol	106-44-5	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
m-cresol	108-39-4	1	μg/L	n.d.	2	mg/kg	n.d.	Not Detected	Not Detected
Additional Parameters									
Dry Mass (Total Solids)	-	-	-	-		%	18.1	-	

#### Remarks:

"n.d." = Not Detected

"N/A" = Not Tested / Not Applicable

ΦSludge results are reported based on dry mass \*Data collection only for polyester production

<sup>&</sup>quot;-" = Not Required to be Test

<sup>^</sup>The test result is based on the calculation of selected element(s) and to the worst-case scenario

<sup>@ =</sup> The amine was detected according to EN ISO 14362-1:2017 with the reducing agent. A similar result was obtained from the procedure carried out without the reducing agent. According to EN ISO 14362-1:2017 Annex C.2.1.2.2, the amine originated from a source other than azo colorants.

<sup># =</sup> The amine was detected according to EN ISO 14362-1:2017 with the reducing agent. Confirmation procedure was carried out without reducing agent, according to EN ISO 14362-1:2017 Annex C.2.1.2.2, the amine originated from



Date of Report : 02/11/2021 Page 14 of 18

### **TEST PARAMETERS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

ITEMO	040 N	METHODS	ZDHC	l lmit a		
ITEMS	CAS No.	METHODS	Foundational Limit	Progressive Limit	Aspirational Limit	Units
Anions						
Cyanide	-	Wastewater: USEPA 335.2, APHA 4500-CN, ISO 6703-1, 2, 3, ISO 14403-1, 2 or HJ 484 Sludge: With reference to USEPA 9013, USEPA 9014, USEPA 9213, ISO 11262, HJ 745 or CN converted to HCN by reflux-distillation to NaOH followed by colourimetry or ISE	0.2	0.1	0.05	mg/L
Metals						
Total Antimony (Sb)	7440-36-0		0.1	0.05	0.01	mg/L
Total Chromium (Cr)	7440-47-3	Wastewater:	0.2	0.1	0.05	mg/L
Total Cobalt (Co)	7440-48-4	With reference to USEPA 200.7, USEPA 200.8, USEPA 245.1, USEPA 245.2, USEPA 1631 E, USEPA 6010C, USEPA 6020A, ISO 11885, ISO	0.05	0.02	0.01	mg/L
Total Copper (Cu)	7440-50-8	12846, ISO 17294, ISO 17852, ISO 18412, GB 7466, GB 7467, GB 7472, GB 7475, GB 11907, HJ 597, HJ 694, HJ 700, IS 3025 (Part 2), IS 3025	1	0.5	0.25	mg/L
Total Nickel (Ni)	7440-02-0	(Part 41), IS 3025 (Part 42), IS 3025 (Part 47), IS 3025 (Part 48), IS 3025 (Part 49), IS 3025 (Part 52), IS 3025 (Part 54), IS 3025 (Part 65) or acid	0.2	0.1	0.05	mg/L
Total Silver (Ag)	7440-22-4	digestion followed by ICP or ICP/MS analysis Sludge:	0.1	0.05	0.005	mg/L
Total Zinc (Zn)	7440-66-6	With reference to USEPA 3050, USEPA 3051A, USEPA 3060A, USEPA 6010D, USEPA 6020B, USEPA 7471B or acid/peroxide digestion followed by ICP or ICP/MS analysis	5.0	1.0	0.5	mg/L
Total Arsenic (As)	7440-38-2	by 101 Of 101 /Wo dilarysis	0.05	0.01	0.005	mg/L
Total Cadmium (Cd)	7440-43-9		0.1	0.05	0.01	mg/L
Total Lead (Pb)	7439-92-1	Wastewater: With reference to USEPA 200.7, USEPA 200.8, USEPA 245.1, USEPA 245.2, USEPA 1631 E, USEPA 6010C, USEPA 6020A, ISO 11885, ISO 12846, ISO 17294, ISO 17852, ISO 18412, GB 7466, GB 7467, GB 7472, GB 7475, GB 11907, HJ 597, HJ 694, HJ 700, IS 3025 (Part 2), IS 3025 (Part 41), IS 3025 (Part 42), IS 3025 (Part 47), IS 3025 (Part 49), IS 3025 (Part 52), IS 3025 (Part 54), IS 3025 (Part 65) or acid digestion followed by ICP or ICP/MS analysis	0.1	0.05	0.01	mg/L
Total Mercury (Hg)	7439-97-6	Sludge: With reference to USEPA 3050, USEPA 3051A, USEPA 3060A, USEPA 6010D, USEPA 6020B, USEPA 7471B or acid/peroxide digestion followed by ICP or ICP/MS analysis	0.01	0.005	0.001	mg/L
Chromium-Hexavalent (Cr-VI)	7440-47-3, 18540-29-9	Wastewater: With reference to USEPA 218.6, ISO 18412, GB 7467, IS 3025 (Part 52) or solvent extraction and derivatisation followed by UV/VIS analysis Sludge: With reference to USEPA 3060A, USEPA 7196, USEPA 7199 or alkaline digestion followed by colourimetric UV/VIS or colourimetric IC analysis	0.05	0.005	0.001	mg/L



Date of Report: 02/11/2021

Page 15 of 18

#### **TEST PARAMETERS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

ITELLO	CAS No.		ZDHC			
ITEMS		METHODS	Foundational Limit	Progressive Limit	Aspirational Limit	Units
Alkylphenol (AP) & Alkylphenol Ethoxylates (APEOs)						
NP / OP		Wastewater: With reference to ISO 18857-2 or ASTM D7065 followed by GC/MS or LC/MS(-MS) analysis Sludge: With reference to USEPA 3540/3541, USEPA 3550, USEPA 3560, ISO 18857-2 or ASTM D7065 followed by GC/MS or LC/MS analysis		-		
NPEO / OPEO		Wastewater: With reference to ISO 18254-1, ISO 18857-2 or ASTM D7065 followed by GC/MS or LC/MS analysis Sludge: With reference to ISO 18254-1, ISO 18857-2 or ASTM D7065 followed by GC/MS or LC/MS analysis				
		Wastewater:				
Chlorobenzenes & Chlorotoluenes		With reference to USEPA 8260B, USEPA 8270D or solvent extraction followed by GC/MS analysis  Sludge: With reference to USEPA 3540/3541, USEPA 3550, USEPA 3560, USEPA 3650, USEPA 8270 or solvent extraction followed by GC/MS analysis		-		
Chlorophenols		Wastewater: With reference to USEPA 8270D, ISO 14154:2005 or solvent extraction and derivatisation with KOH, acetic anhydride followed by GC/MS analysis Sludge: With reference to ISO 14154, acid/base liquid extraction, acetylation or liquid/liquid extraction followed by GC/MS analysis		-		
		Mastawatan				
Dyes - Azo (Forming Restricted Amines)		Wastewater: With reference to EN 14362-1, EN 14362-3 or solvent extraction with sodium dithonite reduction followed by GC/MS or LC/MS analysis Sludge: With reference to ISO 14362-1, ISO 14362-3 or solvent extraction with		-		
		sodium dithonite reduction followed by GC/MS or LC/MS analysis				
Dyes - Carcinogenic or Equivalent Concern		Wastewater: Solvent extraction followed by LC/MS analysis Sludge: With reference to ISO 16373 or solvent extraction followed by LC/MS analysis		-		
		Wastowator				
Dyes - Disperse (Sensitising)		Wastewater: Solvent extraction followed by LC/MS analysis Sludge: With reference to ISO 16373 or solvent extraction followed by LC/MS analysis		-		
Flame Retardants		Wastewater: With reference to USEPA 527, USEPA 8270, USEPA 8321B, ISO 22032 or solvent extraction followed by GC/MS or LC/MS analysis Sludge: With reference to ISO 22032 or solvent extraction followed by GC/MS or LC/MS analysis		-		



Date of Report : 02/11/2021

Page 16 of 18

#### **TEST PARAMETERS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

				ZDHC REQUIREMENTS			
ITEMS	CAS No.	METHODS	Foundational	Progressive	Aspirational	Units	
			Limit	Limit	Limit		
Glycols		Wastewater: With reference to USEPA 8270 or solvent extraction followed by GC/MS or LC/MS analysis Sludge: With reference to USEPA 8270D, ISO 22892 or solvent extraction followed by GC/MS or LC/MS analysis		-			
Halogenated Solvents		Wastewater: With reference to USEPA 8260B, Headspace, Purge-and-Trap or solvent extraction followed by GC/MS analysis Sludge: With reference to USEPA 5035, USEPA 50211, USEPA 8010 or solvent extraction followed by GC/MS analysis		-			
Organotin Compounds		Wastewater: With reference to ISO 17353 and derivatisation with sodium diethyl dithiocarbamate followed by GC/MS analysis Sludge: With reference to ISO 23161 and derivatisation with sodium diethyl dithiocarbamate followed by GC/MS analysis		-			
Perfluorinated and Polyfluorinated Chemicals (PFCs)  FTOHs (Non-ionic)  Others (Ionic)		Wastewater: With reference to DIN 38407-42 or CEN/TS 15968 and derivatisation with acetic anhydride followed by GC/MS analysis Sludge: With reference to DIN 38407-42 and derivatisation with acetic anhydride followed by GC/MS analysis Wastewater: With reference to DIN 38407-42 or CEN/TS 15968 followed by LC/MS or LC/MS(-MS) analysis Sludge: With reference to DIN 38407-42 followed by LC/MS or LC/MS(-MS) analysis					
Ortho-Phthalates		Wastewater: With reference to USEPA 8270D, ISO 18856 or solvent extraction followed by GC/MS analysis Sludge: With reference to USEPA 3540/3541, USEPA 3550, USEPA 3560, ISO 18856 or solvent extraction followed by GC/MS analysis		-			
Polycyclic Aromatic Hydrocarbons (PAHs)		Wastewater: With reference to USEPA 8270, DIN 38407-39 or solvent extraction followed by GC/MS analysis Sludge: With reference to USEPA 3540/3541, USEPA 3550, USEPA 3560, USEPA 3650, USEPA 8270 or solvent extraction followed by GC/MS analysis					
Volatile Organic Compounds (VOCs)		Wastewater: With reference to USEPA 8260, ISO 11423-1, Headspace, Purge-and-Trap or solvent extraction followed by GC/MS analysis Sludge: With reference to USEPA 5035, USEPA 5021, USEPA 8260, DIN 38407 Part 43 or solvent extraction followed by GC/MS analysis		-			

\*\*\*\*\*




Date of Report: 02/11/2021

Page 17 of 18

# **PIPING PLAN**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311



\*\*\*\*\*



Date of Report : 02/11/2021

Page 18 of 18

#### **SAMPLING PHOTOS**

Factory Name: NSL Textiles Ltd

Factory Address: Servey No: 371-378 KunchalavariPalem, Chandole Post, Cherukupalli (MD), Guntur (Dist), Andhra Pradhesh - 522311

# **RAW WASTEWATER** GPS Data: 16°00'23.004" N, 80°37'31.296 E SAMPLING LOCATION, CLOSE-UP VIEW

